



Sautech Damage Report

Service Provider

Sautech Contact No:	011 768 1790
Physical Address:	34 Stokroos Ave, Breaunanda, Krugersdorp, SA
Email Address:	support@sautech.net
Technician	Robert Gerry

Client

Client Name:	Ruimsig Country Club
Contact:	Megan Spencer
Incident Date:	9 - 10 November 2021
Asset Serial Number:	EP1020241505091576

Description of Damage

With the continuous load shedding these last couple of weeks with power going off and on at least 2 to 3 times a day put the Inverter under a lot of strain. Due to all the power surges it underwent when Eskom power comes back on, the inverter system must have gone faulty during that night and allowed a surge to come through which caused the batteries to explode. A power surge is the only explanation for a lead acid battery to explode.

As a safety precaution we have decided to split the backup load between 2 inverters to keep the main server load separately from the network cabinet load even though the now damaged inverter was more than capable to carry all that load as it used to do for the last couple of years.

Damage Report Completed by:

Technician Name	Robert Gerry
Occupation	IT Manager
Date	17 November 2021