

14-03-16




C1 & C2: ROOF AND RCC WORK COMPLETED,

C3,C4 &C5: OUTER PLASTERING WORK IN PROGRESS,

CLUSTER C: C6: BASEMENT FILLING CONSOLIDATION WORK IN

**PROGRESS** 







14-03-16 H1 & H2:PLINTH BEAM RCC WORK COMPLETED. H4,H5,H6 & H7: BASEMENT GRAVEL FILLING WORK IN PROGRESS. CLUSTER H: H9: FOOTING RCC WORK COMPLETED. H10,H11,H12, & H13.:BASEMENT GRAVEL FILLING WORK IN PROGRESS. H14: EXCAVATION WORK IN PROCRESS

















COMPLETED.

