

River Test Report

| Summary                     |                       |      |      |     |      |      |      |  |
|-----------------------------|-----------------------|------|------|-----|------|------|------|--|
| Serial Number               | BDDGTC032485          |      |      |     |      |      |      |  |
| Configuration Name          | Aborted               |      |      |     |      |      |      |  |
| River EOL Doc Version       | T0_DTU_V2.1           |      |      |     |      |      |      |  |
| Date                        | 24-07-2026_4.51.19 AM |      |      |     |      |      |      |  |
| Operator                    | Charan_13573          |      |      |     |      |      |      |  |
| DUT                         | 1                     |      |      |     |      |      |      |  |
| Cycle time                  | 8.72                  |      |      |     |      |      |      |  |
| Overall Results             | Fail                  |      |      |     |      |      |      |  |
| Results                     |                       |      |      |     |      |      |      |  |
| Cycle time   8.72           |                       |      |      |     |      |      |      |  |
| Power Lines Impedance check | Config DAQ(1)         |      |      |     |      |      | 1.54 |  |
| Power Lines Impedance check | Read RES TP19-TP3     | 5.00 | 0.06 | Inf | Fail | Kohm | 6.78 |  |