# **CorrosionGuard Al**

### **Corrosion Inspection Report**


Image: img61\_jpg.rf.3667f0e26a65e2eea99049744b6601aa.jpg

Time: 2025-08-23 10:14:18 (MYT)

## **Inspection Summary**

Corrosion Detected: PASS (5 spot(s))
Severity: High=1, Medium=0, Low=4

### **Original Image**



### **Detected Corrosion**

