## **CorrosionGuard Al**

**Corrosion Inspection Report** 


Image: img95\_jpg.rf.b538229f27db5311a802b414e2b99130.jpg

Time: 2025-08-23 10:45:55 (MYT)

## **Inspection Summary**

Corrosion Detected: PASS (1 spot(s)) Severity: High=1, Medium=0, Low=0

## Original Image



## **Detected Corrosion**

