## **CorrosionGuard Al**

**Corrosion Inspection Report** 

Image: img90\_jpg.rf.126872a3228c06bf75c93297169a3c2c.jpg

Time: 2025-08-23 13:15:31 (MYT)

## **Inspection Summary**

Corrosion Detected: PASS (4 spot(s))
Severity: High=3, Medium=1, Low=0

## Original Image



## **Detected Corrosion**

