## **CorrosionGuard Al**

**Corrosion Inspection Report** 

Image: img0\_jpg.rf.926a5df791764df3d1c28ae7e76c0b3c.jpg

Time: 2025-08-23 09:30:39 (MYT)

## **Inspection Summary**

Corrosion Detected: PASS (1 spot(s))
Severity: High=1, Medium=0, Low=0

## Original Image



## **Detected Corrosion**

