

WATER SUPPLY SCHEME STATUS REPORT

PHASE 10.14B - FAINT PRINT / NOISY BACKGROUND TEST

SI No	Name of Scheme	GP / VC	Status	Remarks
1	Rani Para Scheme	Damcherra RF	Functional	Normal
2	Khahamthai Para	West Damcherra	Functional	Normal
3	Jalidhan Para Scheme	Uttamjoy VC	Functional	Normal
4	Nilbusan Para Scheme	Kacharicherra	Repair	Motor fault
5	Kamalacherri Scheme	Thumsarai	Functional	Normal
6	Purnaram Para Scheme	Thumsarai	Low source	Tanker used
7	Gouranga Para Scheme	West Damcherra	Repair	Pipe damage
8	Halam Para Scheme	Damcherra	Functional	Normal
9	Serechandra Para	Thumsarai	Low pressure	Tail end

CONTROLLED PDFNOVA OCR TORTURE FIXTURE