



Overview				Site
Inspect N	88954	Page:	1/1	CRAWLEY RTW PRIESTLEY WAY CRAWLEY RH10 9NT
Job No	16944			
Customer	AECOM			
Contact	Michael William	Date	03/10/2024	
Tel	01293 721800			

Pass

ISI Equipment No	Make / Model	Serial No	Client ID
0000152316	Door Powered Vertical		0000152316

Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments

None

Engineer

Carmelo Belfiore