



Job Site

EASTBOURNE DO/IND/RTW,
3 UPPERTON ROAD,
EASTBOURNE,
BN21 1AA

Job Information

Job Number	15697	Reference	1354.100.
Logged	08/07/2024	Job Type	Contract - PUWER
Contact	Siavash Djavan zad	Tel.	01323 536710

Description

Puwer Inspections

Job Equipment

Equipment	Cust Equip	Visit	Status
0000136776 / Door / Powered Rapid	0000136776	1	Done
0000136848 / Door / Shutter Electric	0000136848	1	Done
0000136850 / Air Handling Unit / (All)	0000136850	1	Done
0000700119 / Air Handling Unit / (All)	0000700119	1	Done

Labour Visits

Visit	Engineer	Date
1	Carmelo Belfiore	08/08/2024

Engineer Report

Following site walk around and observing site log book with manager,
3 items not located.

Engineer

Carmelo Belfiore





Overview				Site	
Inspect N	78301	Page:	1/1		
Job No	15697				
Customer	AECOM				
Contact	Siavash Djavanzad	Date	08/08/2024		
Tel	01323 536710				
				EASTBOURNE DO/IND/RTW	
				3 UPPERTON ROAD	
				EASTBOURNE	
				BN21 1AA	

Pass

ISI Equipment No	Make / Model	Serial No	Client ID
0000136776	Door Powered Rapid		0000136776

Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments

None

Engineer

Carmelo Belfiore

Notice of Non-Examination

Overview				Site
Inspect N	78309	Page:	1/1	EASTBOURNE DO/IND/RTW 3 UPPERTON ROAD EASTBOURNE BN21 1AA
Job No	15697			
Customer	AECOM			
Contact	Siavash Djavanzad	Date	08/08/2024	
Tel	01323 536710			

Asset Not Inspected

ISI Equipment No	Make / Model	Serial No	Client ID
0000700119	Air Handling Unit (All)		0000700119

Skipped Inspection

Reason equipment was not inspected	Following site walk around and observing site log book with manager, item was not located.
------------------------------------	--

Engineer

Carmelo Belfiore



Notice of Non-Examination

Overview				Site
Inspect N	78310	Page:	1/1	EASTBOURNE DO/IND/RTW 3 UPPERTON ROAD EASTBOURNE BN21 1AA
Job No	15697			
Customer	AECOM			
Contact	Siavash Djavanzad	Date	08/08/2024	
Tel	01323 536710			

Asset Not Inspected

ISI Equipment No	Make / Model	Serial No	Client ID
0000136848	Door Shutter Electric		0000136848

Skipped Inspection

Reason equipment was not inspected	Following site walk around and observing site log book with manager, item was not located.
------------------------------------	--

Engineer

Carmelo Belfiore



Notice of Non-Examination

Overview				Site
Inspect N	78311	Page:	1/1	EASTBOURNE DO/IND/RTW 3 UPPERTON ROAD EASTBOURNE BN21 1AA
Job No	15697			
Customer	AECOM			
Contact	Siavash Djavanzad	Date	08/08/2024	
Tel	01323 536710			

Asset Not Inspected

ISI Equipment No	Make / Model	Serial No	Client ID
0000136850	Air Handling Unit (All)		0000136850

Skipped Inspection

Reason equipment was not inspected	Following site walk around and observing site log book with manager, item was not located.
------------------------------------	--

Engineer

Carmelo Belfiore

