



Overview				Site
Inspect N	63889	Page:	1/1	<b>GREENFORD IND</b>  TETRIS A40 ROCKWARE AVENUE  GREENFORD  UB6 0AA
Job No	14875			
Customer	AECOM			
Contact	Muhammed Basathia	Date	22/05/2024	
Tel				

## Pass

ISI Equipment No	Make / Model	Serial No	Client ID
20052024007	Shutter Electric	Crawford. 03411. (37050)	609296

### Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

### Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



### General Comments

None

### Engineer

Neil Wheeler