



Overview				Site
Inspect N	88966	Page:	1/1	<div>CRAWLEY RTW</div> <div>PRIESTLEY WAY</div> <div>CRAWLEY</div> <div>RH10 9NT</div>
Job No	16944			
Customer	AECOM			
Contact	Michael William	Date	03/10/2024	
Tel	01293 721800			

## Pass

ISI Equipment No	Make / Model	Serial No	Client ID
0000152276	Door Powered Vertical		0000152276

### Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

### Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



### General Comments

None

### Engineer

Carmelo Belfiore