

Notice of Non-Examination

Overview				
Inspect N	88991	Page:	1/1	
Job No	16944			
Customer	AECOM			
Contact	Michael William		Date	03/10/2024
Tel	01293 72180	00		

Site
CRAWLEY RTW
PRIESTLEY WAY
CRAWLEY
RH10 9NT

Asset Not Inspected				
ISI Equipment No	Make / Model	Serial No	Client ID	
0000152236	Door Powered Vertical		0000152236	

Skipped Inspection	
Reason equipment was not inspected	Inoperative

Engineer

Carmelo Belfiore



Industrial Safety Inspections Ltd 22-23 Amber Business Village Amington

Tamworth
Staffordshire
B77 4RP

Tel: +44 (0) 1675 481779

Email: info@isisafety.com
Web: www.isisafety.com