



Overview				Site
Inspect N	89046	Page:	1/1	CRAWLEY DO/RET 7 THE BOULEVARD CRAWLEY RH10 1AA
Job No	16946			
Customer	AECOM			
Contact	Nuno Dias	Date	03/10/2024	
Tel	01293 574001			

Pass

ISI Equipment No	Make / Model	Serial No	Client ID
000000000000150	Door Automatic Pedestrian		000000000000150

Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments

None

Engineer

Carmelo Belfiore