



Job Site

LEATHERHEAD DO,
STATION ROAD,
LEATHERHEAD,
KT22 7AE

Job Information

Job Number	16940	Reference	1468.100.
Logged	25/09/2024	Job Type	Contract - PUWER
Contact	Dave Haake	Tel.	01372 856700

Description

PUWER Inspectons

Job Equipment

Equipment	Cust Equip	Visit	Status
0000116204 / Air Handling Unit / (All)	0000116204	1	Done
0000116272 / Air Handling Unit / (All) / mot marked	0000116272	1	Done

Labour Visits

Visit	Engineer	Date
1	John Harding	03/10/2024

Engineer Report

None

Engineer

John Harding



Overview				Site
Inspect N	88979	Page:	1/1	LEATHERHEAD DO STATION ROAD LEATHERHEAD KT22 7AE
Job No	16940			
Customer	AECOM			
Contact	Dave Haake	Date	03/10/2024	
Tel	01372 856700			

Pass

ISI Equipment No	Make / Model	Serial No	Client ID
0000116272	Air Handling Unit (All)	not marked	0000116272

Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None



General Comments

None

Engineer

John Harding

Notice of Non-Examination

Overview				Site
Inspect N	88980	Page:	1/1	LEATHERHEAD DO STATION ROAD LEATHERHEAD KT22 7AE
Job No	16940			
Customer	AECOM			
Contact	Dave Haake	Date	03/10/2024	
Tel	01372 856700			
Asset Not Inspected				
ISI Equipment No	Make / Model	Serial No	Client ID	
0000116204	Air Handling Unit (All)		0000116204	
Skipped Inspection				
Reason equipment was not inspected		asset not found as confirmed by site manager Ben Littlewood.		

Engineer

John Harding

