

Notice of Non-Examination

Overview						
Inspect N	88995	Page: 1/1				
Job No	16944					
Customer	AECOM					
Contact	Michael William		Date		03/10/2024	
Tel	01293 72180	0				

Site
CRAWLEY RTW
PRIESTLEY WAY
CRAWLEY
RH10 9NT

Asset Not Inspected					
ISI Equipment No	Make / Model	Serial No	Client ID		
0000152318	Door Powered Horizontal		0000152318		

Skipped Inspection	
Reason equipment was not inspected	Inoperative

Engineer

Carmelo Belfiore



Industrial Safety Inspections Ltd 22-23 Amber Business Village Amington Tamworth

Tamworth
Staffordshire
B77 4RP

Tel: +44 (0) 1675 481779

Email: info@isisafety.com Web: www.isisafety.com