

Notice of Non-Examination

Overview						
Inspect N	88993	Page:		1/1		
Job No	16944					
Customer	AECOM					
Contact	Michael William		Date	Э	03/10/2024	
Tel	01293 72180	00				

Site
CRAWLEY RTW
PRIESTLEY WAY
CRAWLEY
RH10 9NT

Asset Not Inspected				
ISI Equipment No	Make / Model	Serial No	Client ID	
0000152216	Door Powered Vertical		0000152216	

Skipped Inspection	
Reason equipment was not inspected	Inoperative

Engineer

Carmelo Belfiore



Industrial Safety Inspections Ltd 22-23 Amber Business Village Amington

Tamworth
Staffordshire
B77 4RP

+44 (0) 1675 481779

Email: info@isisafety.com Web: www.isisafety.com

Tel: