



Overview				Site	
Inspect N	78079	Page:	1/1		
Job No	15696				
Customer	AECOM				
Contact	Marc Meeten	Date	07/08/2024		
Tel	01903 882510				
				ARUNDEL DO	
				2 HIGH STREET	
				ARUNDEL	
				BN18 9AA	

Pass

ISI Equipment No	Make / Model	Serial No	Client ID
0000215360	Door Powered Horizontal		0000215360

Asset Photograph

Capture photograph of Asset, including asset number	None
---	------

Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	None
Tolerable - Observations	None

Engineer

Carmelo Belfiore

