**Apex Studios**

# Building Check - Common Areas Interior

**Checklist**

Building Check - Common Areas Interior

**Status**

Checklist Completed

**Checklist Complete**

Gerhard van der Merwe
Sun, 27 Sep 2026 05:40 am

**Reference Number**

APEX_-CL-26004723

**Building**

Gauteng
Apex Studios

**Checklist Score**

13 / 13 (100.00%)


## Common Areas Interior

**Score: 100%** (13/13)

**Carpets in acceptable condition?**

Yes


**Upload picture**



**Ceiling in acceptable condition?**

Yes


**Upload picture**



**Cleaning register signed and updated?**

Yes

**Upload picture**




---

**Door frames in acceptable condition?**

Yes

**Upload picture**



---

**Doors, handles, hinges, kick plates in acceptable condition?**

Yes

**Upload picture**




---

**Floor skirtings in acceptable condition?**

Yes

**Upload picture**




---

**Floor tiles in acceptable condition?**

Yes

**Upload picture**



---

**Is lighting level adequate?**

Yes


**Upload picture**




**Is ventilation adequate?**

Yes

**Upload picture**




**is lift lobbies painting in acceptable condition?**

Yes

**Stair handles in place?**

Yes


**Upload picture**



**Stairs strips in place?**

Yes

**Upload picture**



**Walls painting or wall paper in acceptable condition?**

Yes

**Upload picture**



## Checklist Score

| Section | Total | Score |
|---|---|---|
| Common Areas Interior | 13 / 13 | 100% |
| **Total** | **13 / 13** | **100%** |