Apex Studios

Building-check - Equipment

Checklist

Building-check - Equipment

Status

Checklist Completed

Checklist Complete

Gerhard van der Merwe
Sun, 27 Sep 2026 06:21 am

Reference Number

APEX_-CL-26004727

Building

Gauteng
Apex Studios

Checklist Score

21 / 21 (100.00%)

Equipment

Score: 100% (21/21)

All Air-conditioning in good working order?

Yes

Upload picture



Date of last service

03/07/2026

Biometrics readers in a workable condition?

Yes

Upload picture



Facial readers in a workable condition?

Yes

Upload picture



Door card reader in a workable condition?

Yes

Upload picture



Turnstiles in a workable condition?

Yes


Upload picture



CCTV cameras in good working condition?

Yes


Upload picture



CCTV monitors in good working condition?

Yes

Upload picture



Extractor fans in good working condition?


Yes

Upload picture



When was last fire drill conducted? 06/05/2026

Upload fire drill register



Fire panel in good working condition? Yes

Upload picture



Date of last service 04/08/2026

Fire Equipment last service date? 31/12/2025

Fire extinguishers in good working condition? Yes

Upload picture



How many fire extinguishers? 96

Fire hose reels in good working condition? Yes

Upload picture



How many hose reels? 47

Fire hydrants in good working condition? Yes

Upload picture



How many fire hydrants? 14

Are the fire pumps in good working condition? Yes

Upload picture



How many fire pumps? 2 - 1 Primer pump and 1 main high rise pump

Last fire pumps service date? 12/12/2022

Are generators in good working condition? Yes

Upload picture



Date of last service 29/07/2026

Size of generator? 600KVA x 2

Are heatpumps in good working condition? Yes

Upload picture



Date of last service 22/09/2026

Is the Inverter installation in good working condition? Yes

Date of inverter installation? 12/12/2022

Are batteries in good working condition? N/A

Are lifts in good working condition? Yes

Upload picture



How many lifts? 3

Where is lifts service records kept in? Filing

Date of last Annexure B? 03/06/2026

Are the booster pumps in good working condition? Yes

Upload picture



Date of last service 05/08/2026

Number of booster pumps? 3 Service pending

Are the sump pumps in good working condition? Yes

Upload picture	
Date of last service	05/08/2026
Water Purifying last testing date?	08/09/2026
Water purifying plant working and in good condition?	Yes
WIFI Provider	Captive networks
WIFI SLA in place?	Yes

Checklist Score

Section	Total	Score
Equipment	21 / 21	100%
Total	**21 / 21**	**100%**