Apex Studios

Building-check - External & Internal

Checklist

Building-check - External & Internal

Status

Checklist Completed

Checklist Complete

Gerhard van der Merwe
Sun, 27 Sep 2026 06:30 am

Reference Number

APEX_-CL-26004728

Building

Gauteng
Apex Studios

Checklist Score

23 / 24 (95.83%)

External & Internal

Score: 95.83% (23/24)

General appearance of the building.	9 / 10
Shop fronts in a good condition?	Yes
Upload picture	
Walk off carpets in a good condition?	Yes

Upload picture



Doors in a good condition? Yes

Upload picture



Entrance Sliding door in a workable condition? Yes

Sliding door last service date? 06/08/2026

Gate Motor operational Yes

Upload picture



Roller shutter operational? Yes

Upload picture



Roller shutter last service date 05/08/2026

Boom gate operational? Yes

Basement parking lights in a workable conditions? Yes

Upload picture



Parking Lines clear and visable?

Yes

Upload picture



Planter box lights in a workable condition?

Yes

Spotlights in a workable condition?

Yes

Upload picture



Walls in good condition?

Yes

Upload picture



Window putty in good condition?

Yes

Upload picture



Windows in good condition?

Yes

Upload picture



Anchor Bolts last service date.	05/08/2026
Anchor Bolts next service date.	05/08/2027

Checklist Score

Section	Total	Score
External & Internal	23 / 24	95.83%
Total	**23 / 24**	**95.83%**