Apex Studios

Building-check - Refuse Area

Checklist

Building-check - Refuse Area

Status

Checklist Completed

Checklist Complete

Gerhard van der Merwe
Sun, 27 Sep 2026 14:22 pm

Reference Number

APEX_-CL-26004735

Building

Gauteng
Apex Studios

Checklist Score

2 / 2 (100.00%)

Refuse Area

Score: 100% (2/2)

Waste management SLA in place?	Yes
SLA expiry date	31/12/2026
Waste Management Service Provider?	Global Waste
How frequently do they collect per week?	2 -3
Was there bins broken during the month?	Yes
How many?	0
Was it replaced?	Yes
How many bins on site?	44

Checklist Score

Section	Total	Score
Refuse Area	2 / 2	100%
Total	**2 / 2**	**100%**