Apex Studios

Building-check - Structure

Checklist

Building-check - Structure

Status

Checklist Completed

Checklist Complete

Gerhard van der Merwe
Sun, 27 Sep 2026 14:44 pm

Reference Number

APEX_-CL-26004739

Building

Gauteng
Apex Studios

Checklist Score

6 / 6 (100.00%)

Structure

Score: 100% (6/6)

Basement clean?

Yes

Upload picture



Bollards in good working order?

Yes

Upload picture



Concrete slabs in good condition?

Yes

Upload picture



Curbs in good order?

Yes

Upload picture



Fencing / boundary walls in good order?

Yes

Upload picture



Wall structure in good condition?

Yes

Upload picture



Checklist Score

Section	Total	Score
Structure	6 / 6	100%
Total	**6 / 6**	**100%**