Apex Studios

Building-check - Student Laundry Room

Checklist

Building-check - Student Laundry Room

Status

Checklist Completed

Checklist Complete

Gerhard van der Merwe
Sun, 27 Sep 2026 14:58 pm

Reference Number

APEX_-CL-26004740

Building

Gauteng
Apex Studios

Checklist Score

16 / 16 (100.00%)

Student Laundry Room

Score: 100% (16/16)

Washers in good working order?	Yes
Upload picture	
Maytag washer brands on site?	0
Speed Queen washer brands on site?	30
Dryers in good working order?	Yes

Upload picture



Speed Queen dryer brands on site?	30
Maytag dryer brands on site?	0
Are all machines labelled?	Yes

Upload picture



Last service date?	23/09/2026
Wash basins in good working order?	Yes

Upload picture



Number of wash basins	4
Modems in good working order?	Yes

Upload picture



Number of modems	6
Indoor drying laundry stand in good order?	Yes

Upload picture



Number of laundry stands 1

Ironing boards in good order? Yes

Number of ironing boards 3

Daily filter cleaning done? Yes

Extractor fans in a good conditions? Yes

Upload picture



How many lost laundry cards was replaced for the month? 0

Student unit numbers of lost laundry cards? 0

Was it charged to the account? Yes

Are ther washers in the basement? Yes


Number of washers in the basement 0

Are ther dryers in the basement? Yes

Number of dryers in the basement 0

Cleaning register signed and updated? Yes

Upload picture



Laundry posters visible, neat and updated? Yes

Upload picture



Decoder in a workable condition?	Yes
TV`s in a workable condition?	Yes
Washing lines in a workable condition?	N/A

Checklist Score

Section	Total	Score
Student Laundry Room	16 / 16	100%
Total	**16 / 16**	**100%**