Apex Studios

Building-check - Student Study Room

Checklist

Building-check - Student Study Room

Status

Checklist Completed

Checklist Complete

Gerhard van der Merwe
Sun, 27 Sep 2026 15:03 pm

Reference Number

APEX_-CL-26004741

Building

Gauteng
Apex Studios

Checklist Score

12 / 12 (100.00%)

Student Study Room

Score: 100% (12/12)


Aircon in a workable condition?	Yes
Upload picture	
Any broken equipment?	Yes
Bean Bags in good condition?	Yes
Bibo in a workable condition?	N/A
Blinds in a good condition?	Yes

Upload picture



Carpets in a good condition? Yes

Upload picture



Tables in working condition? Yes

Upload picture



Number of tables 32

Chairs in working condition? Yes

Upload picture



Number of chairs 42

Desk dividers in good condition? Yes

Upload picture



Number of desk dividers 42

Bins in working condition? Yes

Upload picture



Number of bins 1

Light bulbs in a working condition? Yes

Upload picture



Sufficient plugs? Yes


Upload picture



White board in working condition? N/A

Cleaning register signed and updated? Yes

Upload picture



Checklist Score

Section	Total	Score
Student Study Room	12 / 12	100%
Total	**12 / 12**	**100%**