



Libra Valuers

TEJAS DAVE - BE-Civil, MBA-(Fin),
MVAL-Real Estate, MRICS, FIV, FIE, CE, PETA, CVSRT
Shop No.12, Shanti Garden CHS, Sec-5, Building No.7,
Mira Road (E), Mumbai 401107.

Off : 9769070154
 Email :tejas.dave@libravaluers.com
 Web : www.libravaluers.com

VALUATION REPORT

Branch Name	Aditya Birla Finance Ltd - Goregoan -10th Floor	Type of Case	LAP
Valuer Name	Libra Valuers	Date of Visit :	07-05-2021
Case Ref. No	0	Valuation Report- Negative/Positive :	Positive
		Date of Report :	02-06-2021
Contacted Person for property inspection (Name/ Mobile)		Bhavesh-9137869447	

BASIC DETAILS

1	Owner/s Name/s	Mr. Ahmed Mahamad Vasta	
	Applicant/s Name/s	Mahabulls infra engineers Pvt Ltd	
2	Originally type of property	Industrial gala	Industrial
3	Address as per request	Unit no- 5, Ground Floor, Mahabulls infra engineers Pvt Ltd, Shree Sai Commercial Premises Co Op Soc Ltd, Opp Waman Patil Industrial Estate, Waman Tukaram Patil Marg, Amar Nagar, Ghatla, Chembur East Mumbai, Maharashtra 400071	
	Address at site	Unit no- 5, Ground Floor, Mahabulls infra engineers Pvt Ltd, Shree Sai Commercial Premises Co Op Soc Ltd, Opp Waman Patil Industrial Estate, Waman Tukaram Patil Marg, Amar Nagar, Ghatla, Chembur East Mumbai, Maharashtra 400071	
	Address as per document	Unit no- 5, Ground Floor, Mahabulls infra engineers Pvt Ltd, Shree Sai Commercial Premises Co Op Soc Ltd, Opp Waman Patil Industrial Estate, CTS No.5353/24 & Survey No.58(P) at Village Borla, Waman Tukaram Patil Marg, Amar Nagar, Ghatla, Chembur East Mumbai, Maharashtra 400071	
	Pin code of the property	400071	
	Latitude:	19.049067	Longitude: 72.9097
	Main Locality of the Property:	Middle Class	Sub Locality of the Property: Developed
4	Has the valuator done valuation of this property before this? If yes, when, for whom?	NA	

SOUROUNDING & LOCALITY DETAILS

5	Location	Type (Comm., Res, Ind, Mix)	Industrial gala	
		Locality (Low, Medium, Posh)	Middle Class	
		Site is (Dev, Under Dev)	Developed	
		Proximity to civic amenities/	1.7 kms from Govandi Railway station	
		Public transport		
		Railway Station	1.7 kms from Govandi Railway station	 Km
		Bus Stop	Juice Company Bus Stop	 Km
6	Close Vicinity/Landmark	Opp. Wadhwa Chember		
7	Distance from City Center	1.7 kms from Govandi Railway station		
8	Condition and approx width of approach road to reach the property	15 Feet Approx		
9	Physical approach to the property as per site visit (Clear / Not Clear)	Clear		
10	Legal approach to the property as per documents (Clear / Not Clear)	Clear		
11	Any other features like board of other financier indicating mortgage, notice of Court/any authority which may effect the security	No		

PROPERTY DETAILS

12	Occupant	Vacant/Occupied	Tenant occupied	
		Name of Occupant	Royal Enfield Service Centre	
		Relation with applicant	Tenant Occupied	
13	Building details	Property Demarcation (Yes/No)	Yes	
		Property Identified (Yes/No)	Yes	
		Property Identified through	Technical doc	
		Type of structure	RCC Frame structure	
		Land/Plot Area	0	
		No of Blocks if applicable	Single Building	
		No of Units on floor	09 Units	
		No. of Floors	Ground+1st Floor	
		No. of Lifts	No Lift	

		Amenities Available (e.g. Swimming Pool, Club House, etc.)	Security,CCTV Camera			
		Delivery Agency (Public Sector Agency, Co-operative Society,Pvt. Builders, Self-Construction etc.)	NA			
14	Unit details	Property located on Floor Number	Ground Floor			sqft.
		No. of rooms	1 / Industrial Unit			
		Applicable area as per measurement	3348			
		Area as per document	2880 Sq Ft BUA (As per Agreement)			
		Carpet area as per Plan	3348 BUA area as per Architect plan			
		Remarks on view from property (Park/ Main Road /Other Building/sea etc)	Building View			
15	Quality of construction (Good / Avg./ Bad)	Average	Exteriors	Average	Interiors	Average
16	Age of the property considering max age of property as 60 yrs	40 Years as per site Information	Residual life considering max age of property as 60 yrs	20 Years		
SANCTION PLAN APPROVAL & OTHER DOCUMENTS DETAILS						
17	Sanctioned plans verified with approval no/OC/CC	Plan Not provided, , Not provided, Not Provided				
18	Ownership type (Leasehold/ Freehold)	Free Hold				
19	Property documents verified	Reg Agreement for Sale Development permission letter Share Certificate Tax copy Architecture's plan & Architecture's Letter Society letter				
20	Is the property within Municipal Limits	NA				
22	Permissible usage allow as per master plan	Industrial				
23	Whether property under demolition list as per authority (Y/N)	No				
24	Setbacks	As per plan/ Bye laws	Actual at site	Deviation	Remarks, if any	
	Front	NA	NA	NA	NA	
	Side1(Left)	NA	NA			
	Side2(Right)	NA	NA			
	Rear	NA	NA			
25	Floor Wise Area (In Sft.)					
	Floor	Sanctioned/Permissible/area		Total Constructed		Deviation
	Basement Floor	0		0		0
	Stilt Floor	0		0		0
	Ground Floor	0		0		0
	First Floor	0		0		0
	Second Floor	0		0		0
	Third Floor	0		0		0
VALUATION						
26	(A)Description of Constructed Area and Rates					
	For Row House /Plots/ Villa and Bungalow	Description		Area (Sft.)	Rate (Sft.)	Amount
		Land Area		0	0	0
		Construction rate (as on date)		0	0	0
		Loading Considered on Carpet Area		1.0 (As per BUA)	NA	1.0 (As per BUA)
	For Flat /Office/Shops/Builder Floors		Applicable Area	2880	15000	43200000
	Stage of construction in %		100%	Stage of Recommendation in %		100%
	(B)Value of Extra Amenities if applicable					
	Car Parking	PLC	IDC	EDC	Power Backup	Other
	0	NA	NA	NA	NA	0
	Total Amenities charges		0			
	Total Market Value of Property as on Date (A+B)			43200000		
	Guideline Value of The Property			NA		
	Realizable Value			38880000		
	Forced Sale Value			30240000.00		
	Insurance Value			4017600		
	Approx. Rentals in case of 100% complete property			Rs-	230000	
BOUNDARIES						
27	BOUNDARIES		EAST	WEST	NORTH	SOUTH
	As per deed		NA	NA	NA	NA
	At site		W T Patil Marg	Road	Industrial estate	Slum
	Boundaries Matching		NA			

Remarks:-

1. The property under consideration is Industrial Unit in G+1 storied commercial building without lift.
2. The unit has a height of 12 ft Approx.
3. As per site observation access to the building is as per norms and road width is 15 feet approx.
4. We have received Reg Agreement for Sale Share Certificate Tax copy Architect plan & Architect Letter & Society clarification letter are made available for verification.
5. No technical documents are provided. Hence kindly check the OC CC & Sanctioned Plan at your end before disbursement.
6. At the time of visit we have observed that property was tenant occupied by Royal Enfield service center.
7. Agreement made between Mr. Premji Dukaji Rajput AND Mr. Ahmed Mahamad Vasta Dated.05/03/2002 are made available for verification.
8. No Technical Documents provided as the age of the property more than 40 years we releasing report on the basis of provided documents as per institute policy.
9. Unit boundaries are not mentioned in available documents hence Please check at your legal end before disbursement.
10. We have received Architect plan for demarcation of the property which is to be noted.
11. We have considered BUA as per provided agreement to furnish the report.
12. Due to ongoing Covid 19 Pandemic outbreak National wide lockdown transactions are not being carried out / evidences are not available and hence opinion is based on the database of pre lockdown period. Since market activity is impacted in most of the sectors this has led to uncertainty relating to many factors that subsequently impact on the real estate sector. Market Value may change more rapidly and significantly than during standard market conditions. Given the unknown future impact that Covid 19 might have on the real estate market. We therefore recommend that this appraisal should kept under consistent review and real time modifications / additions shall be incorporated subsequently.

30.**Declaration:-**


- Our representative has visited this site. I/We have not verified the title deeds of the properties with the records of the registrar's office as this is beyond the agreed scope of work. Assumptions are made to the best of our knowledge and belief. Reliance is based on the information furnished to us by the identifier AND/OR client.
- The valuer shall not be responsible for the matters of legal nature that affects the value and opinion expressed by us.
- where a sketched plan is attached to this report, it does not purport to represent accurate architectural plans. Sketch plans and photographs are provided as general illustrations only. Documents furnished to us are returned to the client along with the report. We cannot preserve them.
- Fair market value indicated in the report is an opinion of the value prevailing on the date of the said report and is based on market feedback on values of similar properties. Client is free to obtain other independent opinions on the same. Fair, market value of such properties / localities may increase or decrease, depending on the future market conditions & scenarios. value varies with the purpose & date. This report is not to be referred if the purpose is different other than mentioned. No structural survey was conducted by us as it is not in our scope of work
- We hereby declare, "The information furnished above is true and correct to the best of our knowledge and belief. We have no direct or indirect interest in the assets valued.

Sign & Stamp:

Name of Engineer who visited the property:-


NA

(Authorized Signatory)



Longitude, Latitude: 19.049067, 72.9097

Property Sketch



Bank Name:- Aditya Birla Finance Ltd - Goregoan -10th Floor

Customer Name:- Mahabulls infra engineers Pvt Ltd

Postal Address:- Unit no- 5, Ground Floor, Mahabulls infra engineers Pvt Ltd, Shree Sai Commercial Premises Co Op Soc Ltd, Opp Waman Patil Industrial Estate, Waman Tukaram Patil Marg, Amar Nagar, Ghatla, Chembur East Mumbai, Maharashtra 400071

Photographs:



Sat May 08 2021 11:58:59 GMT+0530 (India Standard Time)



Sat May 08 2021 11:59:56 GMT+0530 (India Standard Time)

Two photographs from inside & kitchen photographs (in case of residential unit) are mandatory.



Sat May 08 2021 11:58:58 GMT+0530 (India Standard Time)




Sat May 08 2021 12:01:12 GMT+0530 (India Standard Time)



Sat May 08 2021 11:58:59 GMT+0530 (India Standard Time)



Sat May 08 2021 12:02:18 GMT+0530 (India Standard Time)



Sat May 08 2021 12:02:54 GMT+0530 (India Standard Time)


****Note: Below mentioned declaration will be applicable for Khasra funding properties only. It shall be captured on last page of report and shall have the customer's signature for record purposes.**

Self-declaration - "Myself _____ s/o _____ resident of

_____ declare that property photographs shown above are of the same property against which I/we
applied for loan from the Bank having address _____"

Signature

Annexure



Shree Sai Commercial Premises Co-op. Soc. Ltd.

(REGN. NO. MUM/WM/GNL (O)/9814/2008-2009/ yr. 2008)

Plot No. 4, Amar Nagar, W.T. Patil Marg, Chembur, Mumbai - 400 071.

TO WHOM SO EVER IT MAY CONCERN

Shree Sai Commercial Premises Co-operative Society Ltd is situated on CTS No – 652, Amar Nagar, W.T. Patil Marg, Opp. Waman Patil Ind. Estate, Chembur East, Mumbai – 400 071, FSI of our plot is 1,

The layout plan dated 30th May, 2021, submitted by Architect shri .Meet Chavda having License No. CA/2016/77887 is correct as per our society records.

Thanking You.

Yours Faithfully,

For Shree Sai Commercial Premises Co-op. Soc. Ltd.

Date: 2-6-2021

