

**INCIDENT DETAILS**

<b>Incident Number</b>	<b>0623/25/UK/ROAM (102790)</b>
<b>Handling Office</b>	<b>SANTOS</b>
<b>Status</b>	<b>Outstanding</b>
<b>Vessel's Name</b>	<b>SIMPLE HONESTY</b>
<b>Arrival Date</b>	19/11/2024
<b>Date of Incident</b>	24/11/2024
<b>Voyage/Leg</b>	
<b>Client</b>	<b>United Kingdom Mutual Assurance Association (Bermuda) Ltd,</b>
<b>Client Reference</b>	KK/2024/008367
<b>Members</b>	<b>Fukunaga Kaiun KK</b>
<b>Managers</b>	<b>Fukunaga Kaiun KK</b>
<b>Place of Incident</b>	SAO FRANCISCO DO SUL
<b>Reporting Date</b>	29/10/2025
<b>Type of Incident</b>	Cargo Damage
<b>Local Agent</b>	Unknown
<b>Latest Report to Client</b>	29/10/2025
<b>Incident Reported By</b>	P&I Club
<b>Description of Incident</b>	Allegedly damages to four steel coils. See claim details.

**CARGO INFORMATION**

<b>Bill(s) of Lading</b>	<b>SH26TJSF035, SH26TJSF036, SH26TJSF037, SH26TJSF038</b>
<b>Shipper(s)</b>	QINGDAO HEGANG NEW MATERIAL TECHNOLOGY
<b>Receiver(s)</b>	REGIONAL TELHAS IND. COM. PROD. SID. LTDA.
<b>Port(s) of Loading</b>	XINGANG
<b>Port(s) of Discharge</b>	SAO FRANCISCO DO SUL
<b>Containers' Number(s)</b>	N/A
<b>Type of Cargo</b>	Steel Products
<b>Description of Cargo</b>	1006 prime newly produced pre-painted zinc-aluminium-magnesium coated steel sheet in coils

**CLAIM DETAILS**

<b>Claim Received Date</b>	29/10/2025
<b>Subrogated Claimant</b>	AKAD SEGUROS
<b>Claimant's Reference</b>	16020
<b>Claim Currency</b>	Brazilian Real
<b>Claim Amount</b>	34102.30
<b>Type of Loss</b>	Mechanical Damage (Breakage and/or Crushing)
<b>Cause of Loss</b>	Unknown
<b>Claim Description</b>	Clemente & Domesi Advogados acting to the insurers approached UK Club directly