

**A K C M INSU. AUXILIARY PRIVATE LIMITED**REG. OFFICE :14 A (D BLOCK BASEMENT), FACTORY ROAD,
(NEAR SAFDARJUNG HOSPITAL), NEW DELHI-110 029

TEL : +91- 62396-45920 EMAIL : AKCM.HO@GMAIL.COM, PI@AKCM.CO.IN

REPORT ID:536567

FOUR WHEELER INSPECTION REPORT INSPECTION DATE:10-05-2021 INSPECTION TIME: 11:37:57

INSPECTION ADDRESS : ASHOKA COLONY KARNAL

COMPANY NAME	FUTURE GENERALI INDIA INSURANCE COMPANY LIMITED
BRANCH OFFICE	BRANCH- CHANDIGARH
INSURANCE COMPANY REF NO	37-AKC-090521-090456
REQUESTER NAME	AMIT GUPTA
CUSTOMER NAME	DARSHAN SINGH PAUL
CUSTOMER ADDRESS	17A ASHOKA COLONY KARNAL
VEHICLE NUMBER	HR05AR6916
CHASSIS NUMBER	358850K
ENGINE NUMBER	M837212
ODO METER	26014
RC VERIFIED	YES
VEHICLE MANUFACTURER	HYUNDAI
YEAR OF MANUFACTURE	2015
VEHICLE VARIENT	I 10 ASTA
FUEL USED	CNG
VEHICLE COLOUR	WHITE
ENGINE STARTED	YES

INSPECTION STATUS**REFERRED TO UNDERWRITER**

REMARKS

DUE TO DAMAGES.

Parts	Description	Parts	Description
FRONT BUMPER	SCRATCH	GRILL	SAFE
HEAD LAMP (LT)	SAFE	HEAD LAMP (RT)	SAFE
INDICATOR LIGHT (LT)	SAFE	INDICATOR LIGHT (RT)	SAFE
FOG LAMP (LT)	SAFE	FOG LAMP (RT)	SAFE
FRONT PANEL	SAFE	BONNET	SAFE
LEFT APRON	SAFE	RIGHT APRON	SAFE
LT FRONT FENDER	MINOR DENT	LT FRONT DOOR	SAFE
LT REAR DOOR	SCRATCH	LT PILLAR DOOR (A)	SAFE
LT PILLAR CENTER (B)	SAFE	LT PILLAR REAR (C)	SAFE
LT RUNNING BOARD	MINOR DENT	LT QTR PANEL	SCRATCH
DICKY	MINOR DENT	REAR BUMPER	SCRATCH
TAIL LAMP (LT)	SAFE	TAIL LAMP (RT)	SAFE
RT QTR PANEL	MINOR DENT	RT REAR DOOR	SCRATCH
RT FRONT DOOR	SAFE	RT PILLAR FRONT (A)	SAFE
RT CENTER PILLAR (B)	SAFE	RT PILLAR REAR (C)	SAFE
RT RUNNING BOARD	SCRATCH	RT FRONT FENDER	MINOR DENT
FLOOR / SILENCER	SAFE	UNDER CARRIAGE	SAFE
REAR VIEW MIRROR (LT)	SCRATCH	REAR VIEW MIRROR (RT)	SCRATCH
RIM	SAFE	STEREO / MAKE	SAFE
CD CHANGER / MAKE	SAFE	SEAT COVER	SAFE
CENTER LOCK	SAFE	GEAR LOCKING	SAFE
FRONT W/S GLASS	SAFE	LEFT FRONT DOOR GLASS	SAFE
LEFT REAR DOOR GLASS	SAFE	BACK GLASS	SAFE
TYRES	GOOD	RIGHT FRONT DOOR GLASS	SAFE
RIGHT REAR DOOR GLASS	SAFE	SUN ROOF GLASS	SAFE

OWNER DECLARATION :

I/WE HEREBY CONFIRM THAT THE VEHICLE HAS BEEN INSPECTED IN PRESENCE OF ME/MY/OUR REPRESENTATIVE.

I/WE HEREBY CONFIRM THAT THE IDENTIFICATION DETAILS AND DAMAGES OF VEHICLE AS NOTED/PHOTOGRAPHS TAKEN BY THE INSPECTING OFFICER ARE CORRECT. NOTHING HAS BEEN HIDDEN/UNDISCLOSED.

I/WE AGREED THAT REPAIR/REPLACEMENT OF DENTED/CRACK PARTS & REPAIR PAINTING OF DENTED/SCRATCHED PANELS AS PER THIS INSPECTION PHOTOGRAPHS SHALL BE EXCLUDED IN EVENT OF ANY CLAIM LODGED DURING THE POLICY PERIOD.

I HERE CERTIFY THAT I HAVE SHOWN THE SAME VEHICLE WHICH I HAVE TO GET INSURED AND IF LATER AT THE TIME OF CLAIM IT IS FOUND THAT VEHICLE SHOWN AND ACCIDENTAL ARE DIFFERENT THEN NO CLAIM IS PAYABLE TO ME.

I HERE CERTIFY THAT I WILL NOT CLAIM FOR DAMAGES EXISTING IN MY VEHICLE WHETHER SAME ARE MENTIONED IN REPORT OR NOT IF SAME ARE SEEN IN PHOTOGRAPH TAKEN BY THE INSPECTOR.

EXECUTED BY :
KARNAL KAMAL KUMAR
(TARUN AMBALA)QC DONE BY :
LUDHIANA

CUSTOMER SIGNATURE

29.495163229480386 - 76.98961475864003
10 May 2021 11:37:57
Karnal, Haryana

THIS IS A COMPUTER GENERATED RECEIPT AND DOES NOT REQUIRE ANY SIGNATURE

DOWNLOAD: [IMAGES](#) [VIDEOS](#)TO CHECK AUTHENTICITY OF REPORT
DOWNLOAD ANY " BAR CODE SCAN " APP FROM PLAYSTORE OR APP STORE
USE YOUR SMART PHONE TO SCAN THE QR CODE & CHECK ONLINE RECORD .