

# Camera Calibration Report

## Calibration Information

**Vehicle ID:** 1

**Lens ID:** 368169

**User:** m.haroon@tatweermea.com

**Calibration Date:** 2025-10-28

**Report Generated:** 2025-10-28 10:30:48

## Sharpness Measurements

**Detected Lens:** 35mm

**Sharpness at 10m:** 131.79879350676052

**Sharpness at 20m:** 475.98409879238835

**Sharpness at 40m:** None

**ROIs Detected:** 20m, 10m

## Field Testing

**Status:** ■ Not Tested on Field

## Calibrated Image

Full 112.5 : sharp  
Detected Lens: 35 mm

Make sure to move the lens to the correct position and lock the screws and press 's' to save the image.

