

Camera Calibration Report

Calibration Information

Vehicle ID: 1

Lens ID: 368172

User: m.haroon@tatweermea.com

Calibration Date: 2025-10-28

Report Generated: 2025-10-28 10:44:54

Sharpness Measurements

Detected Lens: 35mm

Sharpness at 10m: 215.12958973530286

Sharpness at 20m: 394.22003214338616

Sharpness at 40m: None

ROIs Detected: 20m, 10m

Field Testing

Status: ■ Not Tested on Field

Calibrated Image

Full 115.3 : sharp

Detected Lens: 35 mm

One of the ROIs is blurry. Please move the lens to the correct position and lock the screws and press 's' to save the image.

