

# Camera Calibration Report

## Calibration Information

**Vehicle ID:** 1

**Lens ID:** 368196

**User:** m.haroon@tatweermea.com

**Calibration Date:** 2025-10-27

**Report Generated:** 2025-10-27 11:32:13

## Sharpness Measurements

**Detected Lens:** 35mm

**Sharpness at 10m:** 106.4304504220196

**Sharpness at 20m:** 546.9318071095362

**Sharpness at 40m:** None

**ROIs Detected:** 20m, 10m

## Field Testing

**Status:** ■ Not Tested on Field

## Calibrated Image

Full 121.7 : sharp

Detected Lens: 35 mm

Make sure to move the lens to the correct position and lock the screws and press 's' to save the image.

