

Camera Calibration Report

Calibration Information

Vehicle ID: 2

Lens ID: 368153

User: m.haroon@tatweermea.com

Calibration Date: 2025-10-28

Report Generated: 2025-10-28 14:25:00

Sharpness Measurements

Detected Lens: 50mm

Sharpness at 10m: None

Sharpness at 20m: 119.6983482488935

Sharpness at 40m: 118.60168736030772

ROIs Detected: 40m, 20m

Field Testing

Status: ■ Not Tested on Field

Calibrated Image

Full 87.9 : blurry

Detected Lens: 50 mm

Make sure to move the lens to the correct position and lock the screws and press 's' to save the image.

