

Camera Calibration Report

Calibration Information

Vehicle ID: 2

Lens ID: 368159

User: m.haroon@tatweermea.com

Calibration Date: 2025-10-28

Report Generated: 2025-10-28 13:36:55

Sharpness Measurements

Detected Lens: 50mm

Sharpness at 10m: None

Sharpness at 20m: 114.34739507789304

Sharpness at 40m: 166.93748570578978

ROIs Detected: 40m, 20m

Field Testing

Status: ■ Not Tested on Field

Calibrated Image

Full 90.0 : blurry

Detected Lens: 50 mm

Make sure to move the lens to the correct position and lock the screws and press 's' to save the image.

