

Camera Calibration Report

Calibration Information

Vehicle ID: 2

Lens ID: 368160

User: m.haroon@tatweermea.com

Calibration Date: 2025-10-28

Report Generated: 2025-10-28 13:27:31

Sharpness Measurements

Detected Lens: 50mm

Sharpness at 10m: None

Sharpness at 20m: None

Sharpness at 40m: 205.95187820179254

ROIs Detected: 40m

Field Testing

Status: ■ Not Tested on Field

Calibrated Image

Full 97.7 : blurry

Detected Lens: 50 mm

Make sure to move the lens to the correct position and lock the screws and press 's' to save the image.

