

# Camera Calibration Report

## Calibration Information

**Vehicle ID:** 2

**Lens ID:** 368193

**User:** m.haroon@tatweermea.com

**Calibration Date:** 2025-10-28

**Report Generated:** 2025-10-28 11:46:22

## Sharpness Measurements

**Detected Lens:** 50mm

**Sharpness at 10m:** None

**Sharpness at 20m:** 118.36566592442256

**Sharpness at 40m:** 172.5652707023515

**ROIs Detected:** 40m, 20m

## Field Testing

**Status:** ■ Not Tested on Field

## Calibrated Image

Full 117.7 : sharp

Detected Lens: 50 mm

Make sure to move the lens to the correct position and lock the screws and press 's' to save the image.

