




In this 3D model, facets appear as semi-transparent to reveal overhangs.

Contents

Lengths	1
Pitch (Degrees)	2
Pitch (on 12)	3
Rafters	4
Azimuth	5
Area	6
Roof Obstructions	7
Imagery	8
Roofing Report Summary	11

Property Address

14755 S 182nd Dr
Goodyear, AZ 85338

Measurements

Area:	5,346 sq ft
Roof Facets:	31
Predominant Pitch:	23°
Number of Stories:	<=1
Ridges/Hips:	364 ft
Valleys:	165 ft
Rakes:	205 ft
Eaves:	308 ft
Estimated Attic:	4,920 sq ft
Roof Obstructions:	29
Roof Obstructions Perimeter:	167 ft
Roof Obstructions Area:	70 sq ft

Prepared for


Jonathan Sutula
JSE Group
5S680 Cloverdale Ct
Naperville, IL 60540-3734
630-399-7805

Lengths

Ridges = 160 ft
Hips = 204 ft
Valleys = 165 ft

Rakes = 205 ft
Eaves = 308 ft
Flashing = 55 ft

Step flashing = 68 ft
Parapets = 0 ft




September 30, 2025
Property Address:
14755 S 182nd Dr, Goodyear, AZ 85338
Report: 67673913



Pitch (Degrees)

Pitches are labeled for facet areas larger than 20 square feet. In some cases, pitch labels have been removed for readability. Flat facets are labeled 'F'.




September 30, 2025
Property Address:
14755 S 182nd Dr, Goodyear, AZ 85338
Report: 67673913




Pitch (on 12)

Pitches are labeled for facet areas larger than 20 square feet. In some cases, pitch labels have been removed for readability. Flat facets are labeled 'F'.



© 2025 Eagle View Technologies, Inc. All Rights Reserved.




September 30, 2025
Property Address:
14755 S 182nd Dr, Goodyear, AZ 85338
Report: 67673913



Rafters

Rafter lengths (rounded to the nearest whole number) over 5 feet. In some cases, segment labels have been removed for readability. Some numbers are prefaced by “+” signs to avoid confusion when rotated (e.g. +6 and +9).




September 30, 2025
Property Address:
14755 S 182nd Dr, Goodyear, AZ 85338
Report: 67673913



Azimuth

The azimuth is the orientation of the structure to true north. In this diagram roof facet directions are labeled in degrees, with 0° (360°) as true north. Flat facets are labeled as 'F'.




September 30, 2025
Property Address:
14755 S 182nd Dr, Goodyear, AZ 85338
Report: 67673913



Area


The area is measured in square feet per roof facet. The values have been rounded to the nearest foot square.



September 30, 2025
Property Address:
14755 S 182nd Dr, Goodyear, AZ 85338
Report: 67673913



Roof Obstructions




September 30, 2025
Property Address:
14755 S 182nd Dr, Goodyear, AZ 85338
Report: 67673913




Imagery

These are images of the property taken from multiple angles.

TOP VIEW




NORTH SIDE




September 30, 2025
Property Address:
14755 S 182nd Dr, Goodyear, AZ 85338
Report: 67673913



SOUTH SIDE




EAST SIDE



September 30, 2025
Property Address:
14755 S 182nd Dr, Goodyear, AZ 85338
Report: 67673913



WEST SIDE



September 30, 2025
Property Address:
14755 S 182nd Dr, Goodyear, AZ 85338
Report: 67673913



Copyright © 2008-2025 EagleView Technologies, Inc. – All Rights Reserved – Covered by U.S. Patent Nos. 8,078,436; 8,145,578; 8,170,840; 8,209,152; 8,515,125.
Other Patents Pending.

ROOFING REPORT SUMMARY

All Structures

Areas per Pitch			
Roof Pitches	3/12	5/12	7/12
Area (sq ft)	23.3	4829.1	493.3
% of Roof	0.4%	90.3%	9.2%

The table above lists each pitch on this roof and the total area and percent (both rounded) of the roof with that pitch.


Structure Complexity		
Simple	Normal	Complex

Waste Calculation									
NOTE: This waste calculation table is for asphalt shingle roofing applications. All values in table below only include roof areas of 3/12 pitch or greater. For total measurements of all pitches, please refer to the Lengths, Areas, and Pitches section below.									
Waste %	0%	3%	8%	13%	16%	18%	20%	23%	28%
Area (Sq ft)	5346	5507	5774	6041	6202	6309	6416	6576	6843
Squares *	53.66	55.33	58.00	60.66	62.33	63.33	64.33	66.00	68.66
	Measured					Suggested			

* Squares are rounded up to the 1/3 of a square

Additional materials needed for ridge, hip, and starter lengths are not included in the above table. The provided suggested waste factor is intended to serve as a guide—actual waste percentages may differ based upon several variables that EagleView does not control. These waste factor variables include, but are not limited to, individual installation techniques, crew experiences, asphalt shingle material subtleties, and potential salvage from the site. Individual results may vary from the suggested waste factor that EagleView has provided. The suggested waste is not to replace or substitute for experience or judgment as to any given replacement or repair work.

All Structures Totals



Total Roof Facets = 31
Total Roof Obstructions = 29

Lengths, Areas and Pitches

Ridges = 160 ft (7 Ridges)
Hips = 204 ft (21 Hips).
Valleys = 165 ft (10 Valleys)
Rakes[†] = 205 ft (19 Rakes)
Eaves/Starter[‡] = 308 ft (32 Eaves)
Drip Edge (Eaves + Rakes) = 513 ft (51 Lengths)
Parapet Walls = 0 (0 Lengths).
Flashing = 55 ft (10 Lengths)
Step flashing = 68 ft (21 Lengths)
Total Roof Obstructions Area = 70 sq ft
Total Roof Area Less Roof Obstructions = 5,276 sq ft
Total Roof Obstructions Perimeter = 167 ft
Predominant Pitch = 5/12
Total Area (All Pitches) = 5,346 sq ft

Property Location

Longitude = -112.4413553
Latitude = 33.3122670

Notes

This was ordered as a residential property. There were no changes to the structure in the past four years.

- † Rakes are defined as roof edges that are sloped (not level).
‡ Eaves are defined as roof edges that are not sloped and level.

September 30, 2025
Property Address:
14755 S 182nd Dr, Goodyear, AZ 85338
Report: 67673913

