

SAFESIGHT AI Inspection Report

Inspection ID: 6a6a86c67d33cac0b4155fe8
Date: 2026-07-30 04:33:34.697814

Metric	Value
Total Images	1
Total Workers	1
Safe Workers	0
Unsafe Workers	1
Overall Compliance	40.0%
Missing Helmets	0
Missing Vests	0
Missing Gloves	1
Missing Boots	1
Missing Goggles	1

image71.jpg

Site: Construction Site A



Workers	1
Safe	0
Unsafe	1
Compliance	0.0%
Status	Unsafe

Missing PPE

- Boots
- Goggles
- Gloves

Worker Details

Worker 1 Status : Unsafe Missing PPE : Gloves, Boots, Goggles

AI Recommendations

• Ensure all workers wear required PPE. • Conduct PPE inspections before work begins. • Replace damaged safety equipment immediately. • Provide toolbox safety talks. • Monitor compliance continuously.

Generated by SAFESIGHT AI

AI-Based Workplace Safety Monitoring System