

FORM MI-014 — VALVE VISUAL INSPECTION CHECKLIST

Mechanical Integrity Department · Ref. SOP-VLV-100

Valve Tag	PSV-2201
Line / P&ID Ref.	P&ID-14-B, Line 6"-HC-2201
Inspection Date	2026-08-20
Inspector	J. Alvarez
Service	Critical — separator isolation, 14 barg

Visual Inspection Findings

Tag / P&ID match	Confirmed, no mismatch
Body / bonnet condition	No external corrosion or pitting observed
Packing gland / flange	Weeping observed at packing gland — rated SEVERE. Continuous drip, visible pooling at base of valve.
Actuator / linkages	No damage; travel stops nominal vs. commissioning setpoint
Handwheel / lever	Smooth operation, no binding, no excessive backlash

Technician Notes & Recommendation

Severe weeping at packing gland photographed (att. 3 photos). Recommend logging on standard Form MI-014 findings report and routing through the normal 48-hour Mechanical Integrity reporting window. No further action taken on shift.

SUBMITTED FOR REVIEW