

COFFEE PACKAGING QUALITY INSPECTION REPORT

Real-Time AI Seal Inspection and Physical Leak Detection

1. Report Information

Packet ID	PKT-20260830021558-A684
Report ID	RPT-20260830-FD27CA
Inspection Date	30 August 2026
Inspection Time	02:17:06 AM
Inspection Module	Packet Seal and Leak Quality Inspection

2. Overall Inspection Summary

Inspection	Result
Real-Time AI Overheat Inspection	NO_OVERHEAT_DETECTED
Physical Packet Leak Test	GOOD
Overall Quality Decision	ACCEPT

3. Final Quality Decision

ACCEPT

No overheat defect was detected during the real-time inspection and the packet passed the physical leak test.

4. Real-Time Two-Stage AI Inspection

Detected Seal Regions	2
Overheat Detected	NO
Highest Overheat Confidence	0.0%
AI Inspection Status	NO_OVERHEAT_DETECTED

Seal-by-Seal Results

Seal	Seal Confidence	Overheat	Overheat Confidence
Seal 1	80.8%	NO	-
Seal 2	69.0%	NO	-

Real-Time Inspection Evidence



5. Physical Packet Leak Detection

Leak Test Result	GOOD
Initial Value	291511
Average Value	216698.29
Threshold	220000
Minimum	214789
Maximum	218215
Range	3426
Reading Count	10
Final Device Status	TOP_REACHED

Load Cell Readings

Reading Number	Sensor Value
1	214789
2	215256
3	215867
4	216387
5	216629
6	217150
7	217214
8	217737
9	217739
10	218215

6. Recommended Action

- Packet passed the current automated quality checks.
- Proceed according to the normal production quality-control process.

7. Inspection System Information

AI Stage 1	Seal Region Object Detection
AI Stage 2	Overheat Defect Object Detection
Camera	IP Webcam Real-Time Video

Physical Controller	Arduino Uno
Force Measurement	HX711 Load Cell System
Mechanical Test	Motorized Packet Pressure Mechanism
Safety / Position Control	Top and Bottom Limit Switches

This report was generated automatically using the coffee packet quality inspection system.