CME JAW-BT-TGR-2086 The Hills Cikupa Banten Inspection Site ID Site Name Location

> Area Photo

Name Plate GPS Kordinat 1 Site Existing





Site View Akses ke site

2 Tower Existing







Shelter for indoor type or RBS foundation for outdoor type





RBS Foundation

RBS Foundation

Cable Tray





Horisontal Cable Tray

Vertical Cable Tray

Inspection Site ID Site Name Location No.	CME JAW-BT-TGR-2086 The Hills Ciklupa Banten		
NO.	Area	Yn.	noto
5	Antenna Mounting 1	Particular Const.	ADDITION OF THE PARTY OF THE PA
		Mounting 1 - Antenna Sector 43 m	Mounting 2 - Antenna Sector 43 m
6	Antenna Mounting 2	The second of th	The second secon
		Mounting 3 - Antenna Sector 40 m	Mounting MW 45 m
7	PLN Connection 1	Panel KWH Closed	The HIIS CRUPA 4662160 011 /L. V. V.)
8	PLN Connection 2	R - N	2002 S-N
9	PLN Connection 3	T - N	R-S
10	PLN Connection 4	Banach Cont.	B429

T - S

Inspection Site ID Site Name Location	CME JAW-8T-TGR-2086 The Hills Cikupa Banten		
No.	Area	Ph	oto
11	PLN Connection 5	2082 C S S S S S S S S S S S S S S S S S S S	BURN ALLERAN
		S - N	S - T
12	Mechanical Electrical (ME)	The second secon	The state of the s
		Panel ACPDB Closed	Panel ACPD Open
13	Grounding 1	AND AND THE STREET, ST	
		Busbar Installed (Upper)	Busbar Installed (middle)
14	Grounding 2		
		Busbar Installed (Lower)	Busbar Installed (IGB)
15	Grounding 3		The second secon

Busbar Installed (EGB)

Bak Kontrol

CME JAW-BT-TGR-2086 The Hills Cikupa Banten Inspection Site ID Site Name Location Area Photo 16 Grounding 4 MGB Pengukuran Grounding ACPDB 17 Grounding 5 Pengukuran Grounding KWH Box Pengukuran Grounding Lower Busbar Grounding 6 Pengukuran Grounding EGB Pengukuran Grounding IGB 19 Grounding 7 Pengukuran Grounding MGB Pengukuran Grounding Cable Tray 20 Other

Other 1

Other 2

Notes

Inpection Site ID Site Name Location CME JAW-BT-TGR-2086 The Hills Cikupa Banten

a series of checklist to verify a minimum requirement to be RFI

No	Area	Scope of Work	OK	Not OK
		Bracket mountings are installed in correct height and degree	Х	
1	Tower	Vertical tray was installed properly	Х	
1	Tower	Horizontal tray was installed properly	Х	
		There is no significant steel member missing	Х	
		Shelter Frame shall be grounded to inspection pit	Х	
		Tower Legs shall be grounded to inspection pit	Х	
		Fence Corners shall be terminated & grounded to perimeter	Х	
		Down Conductor shall be pulled and installed	Х	
2	Crounding and lightning Protection	Air Terminal shall be installed and connected to the down conductor	Х	
2	Grounding and lightning Protection	Bus bar shall be available on the vertical tray and horizontal tray	Х	
		PEB shall be grounded to inspection pit	Х	
		PDB shall be grounded to inspection pit	Х	
		KWH Meter Box shall be grounded	х	
		Grounding value shall be less than 1 Ohm	Х	
		Size shall be appropriate with XL Standard		
3	Shelter for indoor type	Free from leakage		
3		FEB inlet shall be available		
	RBS foundation for outdoor type	Size shall be appropriate with NBWO	х	
	,,	PLN Capacity shall be 13.2 KVA or 13.9 KVA	х	
4	PLN Connection	PLN Voltage shall be 220 V	х	
		BPUJL shall be available	х	
		L1, L2, L3 Fail		
		MSP Failure		
	External Alarms for Indoor Type	Smoke Detektor		
-		High Temp		
5		Door opened		
		AC Removed		
		L1, L2, L3 Fail	х	
	External Alarms for Outdoor Type	MSP Failure	х	
		Check AC functionality		
		Check PDB functionality		
6	Mechanical Electrical (ME)	Check Exhaust Fan		
		Check Shelter Lamp		
		Check Power AC Outlet		
,	14	Site access shall be available	х	
7	Landscape	Paving/gravel and or drainage shall be finished	х	
İ		Status payment to landlord	х	1
		Free from debt from community, supplier and subcont	х	
8	Administration Completeness	Free from community problem	x	1
		Free from government permit probrlem	x	1

Note



## **LAMPIRAN UJI FUNGSI**

DATA PERANGKAT AKAN TERPASANG DAN/ATAU SUDAH TERPASANG MILIK XL(\*)

SPK / ECRF No. (\*\*) : 6612466 Projdef/EWO

SL/B972

2018-06-30 Tanggal Uji Fungsi JAW-BT-TGR-2086

Site ID XL / Candidate Site Name XL

**Tower Provider** Address

The Hills Cikupa PT. Centratama Menara Indonesia

Kp. Soronggo, RT. 004 RW. 006, Desa. Wanakerta, Kec. Sindang Jaya, Kab. Tangerang

**Tower Height** 

Latitude 6°11'25.15"S Longitude 106°29'9.78"E

Antenna RF & Cable Feeder							Ca	Cables	
Item	Status (new / existing / dismantle)	Qty	Height (m)	Model	Dimensions (mm) (LxWxD)	Azimuth	Qty	Size (")	
1.a	New	1	40			30			
1.b	New	1	40			105			
1.c	New	1	40			265			
1.d									
1.e									
1.f									
Note									

	Antenna MW							
Item	Status (new / existing / dismantle)	Qty	Height (m)	Model	Diameter (m)	Azimuth	Qty	Size (")
2.a	New	1	35		0.6	192.39		
2.b								
2.c								
2.d								
Note							_	

	Bandwidth Transport								
Item	Status (new / existing	Current Capacity	Add Capacity						
	/ dismantle)								
3.a									
3.b									

RRU / Others								Cables	
Item	Status (new / existing / dismantle)	Qty	Height (m)	Model	Dimensions (mm) (LxWxD)	Equipment Type	Qty	Size (")	
4.a	New	3	40	2219 B1					
4.b	New	2	40	4415 B3					
4.c									
Note									

	Ground Space							
Item	Status (new / existing	Length (m)	Width (m)	Length x width (m2)	Remark			
	/ dismantle)							
5.a	New	5	1	5x1				
5.b								
5.c								

Akan Terpasang : Seperti tertulis dalam RFA

ECRF: Untuk penambahan / pengurangan / penggantian perangkat

SPK : Untuk New Site (build to suit) / Colocation

## BERITA ACARA UJI FUNGSI

Nomor: 265/BAPS-XL/IMP-CMI/2018

Pekerjaan B2S

Site Name The Hills Cikupa JAW-BT-TGR-2086 Site ID

Pada Hari ini Sabtu tanggal 30 Bulan Juni Tahun 2018

kami yang bertanda tangan dibawah ini:

Nama David S Sianipar

Jabatan Implementation Manager

Dalam hal ini bertindak untuk dan atas nama PT XL Axiata Tbk (selanjutnya disebut "Pihak Pertama") dan

Kitson Hutabarat Nama Project Manager Jabatan

Dalam hal ini bertindak dan atas nama PT. Centratama Menara Indonesia (selanjutnya disebut "Pihak Kedua"),

Berdasarkan kepada

antara PT XL Axiata, Tbk Perjanjian Sewa Menyewa Infrastruktur Tower untuk Makro BTS dengan No. 0179-08-F07-120150 , sebagai berikut:

## Pekerjaan telah selesai dan berfungsi dengan baik 100 % (seratus persen)

Adapun lingkup pekerjaan yang sudah dilaksanakan adalah: penyedian Obyek Sewa berupa:

Sewa Menyewa Infrastruktur Tower untuk Makro BTS

Berita acara ini di buat rangkap 2 (dua) asli untuk kepentingan semua pihak dalam rangka penerbitan Berita Acara Penggunaan Site (BAPS)

> Pihak Pertama PT Ericsson Indonesia

Pihak kedua PT. Centratama Menara Indonesia

TP Signature TraoBBH-06-Hatpa9.55.49 466186 (RFI\_XL\_V1)\_1