

BACKFLOW DEVICE TEST REPORT

COMPANY	242 W Sharon Rd.	DATE	8/29/2024	
STREET	242 W Sharon Rd.	EMAIL	druhe@inclusivehr.org	
CITY, STATE, ZIP	Cincinnati, Ohio 45246	CONTRACT NO.	36410949	
PHONE	(513) 619-2927	INSPECTED BY	Charlie Brandhorst	
DEVICE	Watts	LF007M3QT	169206	3/4"
	Manufacturer	Model	Serial No.	Size
TEST GUAGE TYPE	Midwest 845			
DATE OF LAST CALIBRATION	3/2/2024			

No. 1 Shutoff	☒ Closed ☐ Leaked	METER DETECTOR ASSEMBLY		
No. 2 Shutoff	☒ Closed ☐ Leaked	☐ Pass	☐ Fail	
Line Pressure	Reduced Pressure Principle Assembly		Pressure Vacuum Breaker	
85 PSI	Double Check Valve Assembly			
INITIAL TEST	Check Valve #1	Check Valve #2	Relief Valve	Air Inlet
	☐ Leaked	☐ Leaked	Relief Open @	Opened @
	☒ Closed	☒ Closed	psid	psid
	1.1 psid	1.5 psid	Relief Valve	Did not opened @
			☐ Pass	Check Valve
			☐ Fail	Held @
				Leaked
Repairs and/or Remarks				
FINAL TEST	Tight	Tight	Relief Open @	After repair
	Relief		psid	Date
	psid			

PASSED ☒ FAILED ☐

NOTE: WE RECOMMEND AN EXPANSION TANK ON ANY CLOSED WATER SYSTEM

Remarks	Confined space bypass
---------	-----------------------

In completing and submitting this test report, the Tester certifies that the device has been tested and maintained in accordance with all applicable rules and regulations

Customer's Signature	Customer's Printed Name	Date
	A12807	8/29/2024
Tester's Signature	Test Number	Date