Helett Enterprises

# QC Inspection Record

Outbound shipment

Record no.
**QC-26-00418**

| FBA shipment ID | Inspection date | Appointment |
|---|---|---|
| FBA15K7T2QX9 | 31 Oct 2026 | 02 Nov 2026, 11:30 |

| Product | SKU | Warehouse |
|---|---|---|
| HT20 PRO | HT20-PRO-BLK | DEL4 Delhi |

| Units received | Units inspected | Boxes (this SKU) | Model dispatched |
|---|---|---|---|
| 240 | 240 | 12 | ATS / Drop In |

## A OUTER CARTON

| # | Check | OK | Not OK | N/A | Remarks |
|---|---|---|---|---|---|
| 1 | Carton clean, no dents, tears or water marks | ☑ | ☐ | ☐ | |
| 2 | Carton sealed with tape, no re-taping | ☑ | ☐ | ☐ | |
| 3 | Carton label legible, stuck flat, not covered | ☐ | ☒ | ☐ | box 7 label creased |

## B LABELS

| # | Check | OK | Not OK | N/A | Remarks |
|---|---|---|---|---|---|
| 4 | FNSKU label present and scannable | ☑ | ☐ | ☐ | See FNSKU check below |
| 5 | Label barcode matches product | ☑ | ☐ | ☐ | |
| 6 | MRP printed | ☑ | ☐ | ☐ | |
| 7 | Serial number present | ☑ | ☐ | ☐ | |
| 8 | Shipping label present | ☐ | ☐ | ☑ | box label stage |

## C PRODUCT AND PACKING

| # | Check | OK | Not OK | N/A | Remarks |
|---|---|---|---|---|---|
| 9 | Product condition: no scratches, cracks, dead units | ☑ | ☐ | ☐ | |
| 10 | Inner packaging in good condition | ☑ | ☐ | ☐ | |
| 11 | Polybag / seal intact | ☑ | ☐ | ☐ | |
| 12 | Accessories included as per BOM | ☑ | ☐ | ☐ | |

## D QUANTITY

| Inspected | Accepted | Rejected | Rejection rate |
|---|---|---|---|
| 240 | 236 | 4 | 1.7 % |

## E FNSKU CHECK

| # | Unit to scan | Scanned code | Result | Time |
|---|---|---|---|---|
| 1 | Unit 14 of 240 | X002K9QH4D | FNSKU OK | 10:42:07 |
| 2 | Unit 97 of 240 | X002K9QH4D | FNSKU OK | 10:43:31 |
| 3 | Unit 203 of 240 | X002K9QH4D | FNSKU OK | 10:44:12 |

## F BOX LABEL CHECK

| # | Box to scan | Scanned carton ID | Result | Time |
|---|---|---|---|---|
| 1 | Box 3 of 12 | FBA15K7T2QX9U000003 | LABEL OK | 10:51:20 |
| 2 | Box 7 of 12 | FBA15K7T2QX9U000007 | LABEL OK | 10:52:02 |
| 3 | Box 11 of 12 | FBA15K7T2QX9U000011 | LABEL OK | 10:52:44 |

## G RESULT

Overall result
☑ Good ☐ Satisfactory ☐ Bad

Product condition
☑ Good ☐ Bad

Packaging quality
☑ Good ☐ Bad

QC remarks
*4 units rejected: dead on power-up. Box 7 label creased, relabel before dispatch.*

## H DISPATCH

| # | Date | Transport | Boxes sent | Units | Total so far |
|---|---|---|---|---|---|
| 1 | 02 Nov | Own truck DL1LX 4471 | 12 | 236 | 12 of 12 |
| 2 | | | | | |

| QC | Dispatch | Final Confirmation |
|---|---|---|
|  |  |  |
| Aditi Rao | Amal Helett | R. Kumar |