

Vehicle Transfer Protocol



1. Basic Data

License Plate WI-L 8957E	VIN LB1234567890ABCDE
Make / Model Lynk & Co 08	Mileage 12345 km
Inspector Max Mustermann	Receiver Erika Musterfrau
From CarHandling Campus	To Hamburg
Transfer Type Hinbringen	
Conditions Trocken, Tageslicht	

2. Technical & Fluids

Fuel 80 %	Battery 95 %	Conditions Trocken, Tageslicht
--------------	-----------------	-----------------------------------

3. Checklist

Condition		Equipment	
Floor	Clean	First Aid Kit	Yes
Seats	Clean	Warning Triangle	Yes
Entry	Clean	Vest	Yes
Dashboard	Clean	Charging Cable	No
Trunk	Dirty	Registration	Yes
Engine Bay	Clean	Charging Card	No

4. Remarks

Fahrzeug ohne Auffälligkeiten übergeben.
--

Inspector

M. Mustermann

Max Mustermann

Receiver

E. Musterfrau

Erika Musterfrau

5. Photo Documentation

Vorne

Front

Hinten

Rear

Links

Left

Rechts



Right

Schein

Reg. Doc.

6. Recorded Damages

#	Position	Type	Intensity
1	Front left door	Scratch	Surface
2	Rear bumper	Dent	Medium



Damage 1: Tür vorne links

Damage 2: Stoßfänger hinten

7. Additional Photos





Photo 1

Photo 2

Zusatz 3

Photo 3