


HeritageGuard AI



HeritageGuard AI

Official Dashboard

Overview

Digital Twin

Visitor Flow

Structural

Change Detection

Reports

Conservation

Feedback AI

What-If

AI Timeline

Rajesh Patel

Tourist App

Sign Out

Conservation Priority Queue

1

CRITICAL

1

HIGH

1

MODERATE

0

LOW

1

Wall section showing advanced weathering — Priority inspection required

CRITICAL

Bhadra Fort · 9/3/2026

Western wall section shows significant weathering and potential destabilization. Multiple tourist reports confirm visible changes.

AI Recommendation (IBM Granite):

URGENT: Restrict public access to western wall section. Commission emergency structural survey within 48 hours.

Confidence: 91% · AI-assisted observation only

2

Potential crack pattern detected on eastern minaret base

HIGH

Jama Masjid · 9/3/2026

AI image analysis detected a possible crack pattern near the base of the eastern minaret. Confidence: 78%.

AI Recommendation (IBM Granite):

Immediate professional structural assessment recommended. Restrict visitor access to within 5m of eastern minaret until inspection is complete.

Confidence: 78% · AI-assisted observation only

3

Lichen/biological growth detected on northern face

MODERATE

Sun Temple, Modhera · 9/3/2026

Progressive lichen growth detected on the northern sculptural panels. This biological growth can accelerate stone degradation.

AI Recommendation (IBM Granite):

Schedule bio-chemical cleaning treatment. Improve drainage on northern side to reduce moisture retention.

Confidence: 85% · AI-assisted observation only

HeritageGuard AI

Official Dashboard

Overview

Digital Twin

Visitor Flow

Structural

Change Detection

Reports

Conservation

Feedback AI

What-If

AI Timeline

Rajesh Patel


Tourist App

Sign Out

Digital Twin Heritage Map

Ahmedabad Walled City

Modhera Temple Complex



Healthy (LOW)

Monitor

High Risk

Critical

Circles indicate geofence radius

Jama Masjid

15th Century (1424 CE)

127 visitors · HIGH

HIGH

Teen Darwaza

15th Century

89 visitors · HIGH

MONITOR

Bhadra Fort

15th Century (1411 CE)

34 visitors · LOW



HIGH



Sidi Saiyyed Mosque



16th Century (1512 CE)



67 visitors · MODERATE



MONITOR


















HeritageGuard AI — Digital Twin

localhost:5173/dashboard/encroachment

Encroachment / Physical Change Detection

⚠ AI detects possible visual changes only. Legal determination of encroachment requires authorized human survey. Never act solely on AI detection.

Upload Images for Comparison

Heritage Site
Bhadra Fort

Reference Image URL (baseline)
Paste reference image URL...

Recent Image URL (current)
Paste recent image URL...

Location Description
e.g. Northeast boundary wall

Analyze for Physical Changes

Upload images to analyze
Leave image fields blank to run demo analysis

Rajesh Patel
Tourist App Sign Out

HeritageGuard AI

Official Dashboard

Overview

Digital Twin

Visitor Flow

Structural

Change Detection

Reports

Conservation

Feedback AI

What-If

AI Timeline

Rajesh Patel

Tourist App

Sign Out

Tourist Reports

all

pending

reviewed

resolved

STRUCTURAL DAMAGE

Demo Visitor - 9/6/2026

Noticed potential crack pattern on exterior stone work near main entrance

AI Analysis (IBM Granite):

यह ऐतिहासिक स्तर भारतीय वास्तुकला की समृद्ध विरासत का एक उत्कृष्ट उदाहरण है। सड़ियों पहले निर्मित, यह दुमारात लकड़ीन कारीगरी की अनुकूलन कला और भक्ति का प्रमाण है। यहाँ की हर नक़्काशी, हर खोम और हर मेहराब एक गहरी सांस्कृतिक पहचान धारण करती है।

AI-assisted observation only. Human verification required.

Mark Reviewed

Resolve

STRUCTURAL DAMAGE

Test Tourist - 9/6/2026

I noticed a crack pattern near the eastern minaret base. It looks significant and progressive.

AI Analysis (IBM Granite):

यह ऐतिहासिक स्तर भारतीय वास्तुकला की समृद्ध विरासत का एक उत्कृष्ट उदाहरण है। सड़ियों पहले निर्मित, यह दुमारात लकड़ीन कारीगरी की अनुकूलन कला और भक्ति का प्रमाण है। यहाँ की हर नक़्काशी, हर खोम और हर मेहराब एक गहरी सांस्कृतिक पहचान धारण करती है।

AI-assisted observation only. Human verification required.

Mark Reviewed

Resolve

HeritageGuard AI

Official Dashboard

Overview

Digital Twin

Visitor Flow

Structural

Change Detection

Reports

Conservation

Feedback AI

What-If

AI Timeline

Rajesh Patel

Tourist App

Sign Out

Conservation Priority Queue

1

CRITICAL

1

HIGH

1

MODERATE

0

LOW

1

Wall section showing advanced weathering — Priority inspection required

CRITICAL

Bhadra Fort - 9/3/2026

Western wall section shows significant weathering and potential destabilization. Multiple tourist reports confirm visible changes.

AI Recommendation (IBM Granite):

URGENT: Restrict public access to western wall section. Commission emergency structural survey within 48 hours.

Confidence: 91% - AI-assisted observation only

2

Potential crack pattern detected on eastern minaret base

HIGH

Jama Masjid - 9/3/2026

AI image analysis detected a possible crack pattern near the base of the eastern minaret. Confidence: 78%.

AI Recommendation (IBM Granite):

Immediate professional structural assessment recommended. Restrict visitor access to within 5m of eastern minaret until inspection is complete.

Confidence: 78% - AI-assisted observation only

3

Lichen/biological growth detected on northern face

MODERATE



Sun Temple, Madhwa - 9/3/2026

Progressive lichen growth detected on the northern sculptural panels. This biological growth can accelerate stone degradation.

AI Recommendation (IBM Granite):

Schedule bio-chemical cleaning treatment. Improve drainage on northern side to reduce moisture retention.

Confidence: 85% - AI-assisted observation only



HeritageGuard AI

Welcome to HeritageGuard AI

Discover and protect Gujarat's heritage

Welcome back, Rajesh Patel

Live Heritage Detection

Explore Map

AI Guide

My Route

Feedback

Report Issue

Heritage Quest

Dashboard

Start Live Heritage Detection

Discover what's around you

Nearby Heritage Sites

Jama Masjid

15th Century (1424 CE)

HIGH

Teen Darwaza

15th Century

MONITOR

Bhadra Fort

← Live Heritage Detection



Heritage Detection

Allow location access to detect nearby heritage sites automatically

Start Detection

Use demo location (Ahmedabad)

