PRODUCT PERFORMANCE FEEDBACK REPORT IFAD MOTORS LTD DMS NO: 3362 **Head Office** IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208 23.08.2021 368 Date: F.R SI NO# Ref.No: Moulvibazar/August/368 Engineer Name: Md. Abdullah Al Mchanic Name:Md: Uzzal Mia Zone Name: Moulvibazar Zone Approved by: Mr. Kaushik Sarkar (COO) 01714292233 Mobile No: Customer Name: | Binoy mollik **Kaderia Motors** Dealer Name: Moulvibazar sadar Address: 18060 Present Km MD6M14CL5K4NA0070 CH NO Full # Customer Complain:-TVS KING DURAMAX OL4NK409A0070 **EN NO Full #** The vehicle stopped running Model# CNG Sale Date # 13.08.2020 1st PS Kms 1St PS Date 23.08.2021 Date of Comp# 23.08.2021 Date of Repair# Free service information **2nd Free Service 3rd Free Service 1St Free Service KMs Date KMs** Date **KMs** Date 10530 23.11.2020 3,420 14.02.2021 24.09.2020 940 Observation:- We checked & found that Crankshaft Assy has been broken. Action Taken:- One new Crankshaft Assy, Gasket Cylinder Head & Bloc has been replaced. Failure Particular Approved Rejected Vendor code Part Name Part NO. SL Gasket Cylinder Head 1 01 G4011350 1 01 Gasket Cylinder Blo G4011420 2 01 Crankshaft Assy 3 G4020180 NO ENTRY 4 For Head Office Use **Failure Parts Photo DMS** Engineer **Head of Service**

Ons complete