





		PRODUCT PERFORMANCE FEEDBACK REPORT							
		IFAD MOTORS LTD				DMS NO:			
		Head Office				3400			
IFAD Tower, Plot-7(New), Teigoan Industrial Area, Dhaka-1208									
Ref.No: Mym-89		F.R SI NO# 89		Date: 12.12.21					
Zone Name: Mymensingh		Engineer Name: Md Jahid Hasan		Mchanic Name: Md Forhad Mia					
Approved by:									
Customer Name: Md Masud Rana				Mobile No: 1727762060					
Address: Muktagacha, Mymensingh				Dealer Name: Sadiya Motors					
Customer Complain:-		CH NO Full # MD6M14CL7K4P00226		Present Km 16823					
Engine oil consumption (200 ml consumption per 100 kms run)		EN NO Full # OL4PK4900188		Model # TVS King Duramax					
		Sale Date # 16.11.2020							
		Date of Comp# 08.12.202		1st PS Date 1st PS Kms					
		Date of Repair# Pending		N/A N/A					
		Free service information							
		1st Free Service		2nd Free Service		3rd Free Service			
Observation:- we find and checked that this vehicle Engine oil consumption (200 ml consumption per 100 kms run)									
Action Taken:- Please to be replace the cylinder head assy , Valve intake, valve Exhaust, steam valve oil seal, gasket cylinder head, gasket cylinder block, piston by new one under warranty.									
Failure Particular									
SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected			
1	G4011300	Cylinder head assy	1	Tvs					
2	G4011380	Valve Exhaust	1	Tvs					
3	G4011370	Valve Intake	1	Tvs					
4	G4011350	Gasket cyl head	1	Tvs					
5	G4011420	Gasket yliner	1	Tvs					
6	N4011100	Valve steam oil seal	2	Tvs					
7	G4020130	Piston 66.00	1	Tvs					
Failure Parts Photo		For Head Office Use							
		Head of Service		Engineer		DMS			
									
				Bilal Hossain Dy. Manager (Service) IFAD MOTORS LTD Head Office, Dhaka.		Complete			