



IFAD MOTORS LTD

Head Office

IFAD TOWER, 07 Tejgaon I/A, Dhaka-1208.

DMS JOB NO

2312

Ref.No:	Habiganj/August/315	F.R SI NO#	315	Date:	10.08.2020
Zone Name:	Habiganj Zone	Engineer Name:	Md. Abdullah Al Zabed		
Approved by:	Prabir Biswas (Head of Service & Spare Parts)				
Customer Name:	Shahnuur Miab.		Mobile No:	01703009956	
Address:	Kulaura, Moulvibazar		Dealer Name:	A.J Motors,	
Customer Complain:-	CH NO Full #	MD6M14CA6K4H00011	Present Kms #	18640	
RIM ASSY has been cracks.	EN NO Full #	AK4DK4611739	Model #	TVS KING DELUXE PLUS CNG (Cuft)	
	Sale Date #	Only for road test /			
	Date of Comp#	06.08.2020	1st PS Date	1st PS Kms	
	Date of Repair #	06.08.2020			
	Free service information				
1st Free Service		2nd Free Service		3rd Free Service	
Date	KMs	Date	KMs	Date	KMs
09.10.2019	985	10.12.2019	4920	25.03.2020	9980

Obserbation:- we checked & found that rear two wheel rim assy has been cracks.

Action Taken:- New two rim assy replaced.

Failure Particular						
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected
1	G2111090	RIM ASSY	2	tvS		
2						
3						
4						
5						
6						

Failure Parts Photo	For Head Office Use
	<p>Prabir Biswas</p> <p>3/9/2020.</p> <p>Cuft Vehicle</p>

02/09/2020

Mity Bahar

03.09.2020

DMS complete