


Customer Code: 21302292

<b>TVS</b>		<b>PRODUCT PERFORMANCE FEEDBACK REPORT</b>			
<b>IFAD</b> MOTORS LIMITED		<b>IFAD MOTORS LTD</b>			<b>DMS NO:</b>
		<b>Head Office</b>			<b>3163</b>
<b>IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208</b>					
<b>Ref.No:</b>	<b>Kus</b>	<b>F.R SI NO#</b>	<b>142</b>	<b>Date:</b>	<b>15/02/2021</b>
<b>Zone Name:</b>	<b>Kushtia</b>	<b>Engineer Name:</b>	<b>Md:Hosan ali</b>	<b>Mchanic Name:</b>	<b>Sabuj ali</b>
<b>Approved by: Prabir Biswas (Head of Service,Spare Parts &amp; Production)</b>					
<b>Customer Name:</b>	<b>Abdual mannan</b>	<b>Mobile No:</b>	<b>01405-644548 ,01764-037991</b>		
<b>Address:</b>	<b>Rajbari</b>	<b>Dealer Name:</b>	<b>Anis auto</b>		
<b>Customer Complain:-</b>	<b>CH NO Full #</b>	<b>MD6M14CA4K4K00099</b>	<b>Present Kms # 15561</b>		
<b>1.Vehical dose not start</b>	<b>EN NO Full #</b>	<b>AK4KK4803189</b>	<b>Model #</b>	<b>TVS KING DELUXE</b>	
	<b>Sale Date #</b>	<b>28.02.2020</b>			
	<b>Date of Comp#</b>	<b>20-01-21</b>	<b>1St PS Date</b>	<b>1st PS Kms</b>	
	<b>Date of Repair#</b>				
	<b>Free service information</b>				
	<b>1St Free Service</b>	<b>2nd Free Service</b>	<b>3rd Free Service</b>		
	<b>Date</b>	<b>KMs</b>	<b>Date</b>	<b>KMs</b>	<b>Date</b>
	<b>15-03-20</b>	<b>967</b>	<b>4/7/2020</b>	<b>8,768</b>	<b>15-02-21</b>
<b>15561</b>					
<b>Observation:- Do not start vehicle &amp; compressor low</b>					
<b>Action Taken:- valve &amp; valve oil seal need to Changed</b>					
<b>Failure Particular</b>					
<b>SL</b>	<b>Part NO.</b>	<b>Part Name</b>	<b>Qty</b>	<b>Vendor code</b>	<b>Approved</b>
<b>1</b>	<b>Engine valve kit</b>	<b>G4320780</b>	<b>1</b>		
<b>2</b>					
<b>3</b>					
<b>4</b>					
<b>Failure Parts Photo</b>					
		<b>For Head Office Use</b>			
		<b>Head of Service</b>	<b>Engineer</b>	<b>DMS</b>	
		