ACME
MANUFACTURING

QUALITY INSPECTION REPORT

IR-99211 | Inspection 16 Oct 2026

Inspection ID	**IR-99211**	Related PO	**PO-77821**
Delivery Note	**DN-11000**	Units Available	**940**
Inspector	**J. Wong - Quality**	Location	**Acme Warehouse**
Inspection Date	**16 Oct 2026**	Method	**Visual + count verification**

CLAIM AND VERIFICATION

Category	Reported	Supported	Unsupported
Missing units	60	60	0
Damaged units	70	55	15

QUALITY CONCLUSION
55 units show documented physical damage consistent with warehouse photos W-01 to W-06. An additional 15 units were reported damaged but could not be matched to unique supported evidence.

Inspection observations

#	Observation	Qty	Status
1	Carton deformation / crush damage	21	Supported
2	Bent connector housings	18	Supported
3	Cracked protective casing	16	Supported
4	Additional claimed damage	15	Not sufficiently evidenced

Recommended settlement basis

Ordered quantity	1,000
Less: missing units	-60
Less: supported damaged units	-55
Payable quantity	**885**
Unit price	$18.00
Evidence-supported payable value	**$15,930.00**