

District Report

Okhaldhunga

23-29 March 2018

Activity Summary

Activity	Contact Person	Reference Document
4w has been updated and uploaded in the google drive. In 4w this week one event & 5 rows have been added.	Uttam Parajuli Im.okhaldhunga@hrrpnepal.org	Click Here
Contact list has been updated and uploaded in the google drive. No any Changed has been occurred this week.	Uttam Parajuli Im.okhaldhunga@hrrpnepal.org	Click Here
Enrollment Matrix has been updated and uploaded in the google drive noticeable amount of tranche receiving beneficiaries has been increased.	Uttam Parajuli Im.okhaldhunga@hrrpnepal.org	click here

Upcoming Events & Meetings

Event / Meeting	Date, Time, and Location	Contact Person
General/Technical Coordination Meeting. Main Agendas - Sharing the information and discussion about joint monitoring visit - Updates from Partners, Challenges and discussion on Current Issues	29 th March ,12:00 Pm NRA Meeting hall Okhaldhunga	Sagar Chandra Adhikari techcord.okhaldhunga@hrrpnepal.org Uttam Parajuli Im.okhaldhunga@hrrpnepal.org Prakash Basnet prakash@hrrpnepal.org
Palika level meeting and joint monitoring Visit	4 th April, Sunkoshi RM Okhaldhunga.	Prakash Basnet prakash@hrrpnepal.org
District Technical Workshop and Exhibition	Second week of April	Prakash Basnet prakash@hrrpnepal.org Sagar Chandra Adhikari techcord.okhaldhunga@hrrpnepal.org
To include details of upcoming events and meetings in the next bulletin, please share details with dc.okhaldhunga@hrrpnepal.org by COB Wednesday of each week.		

Housing Typology Report



Ward 4, Molung Rural municipality, Okhaldhunga: Stone masonry structure in mud mortar and Concrete horizontal bands in lintel, seal and DPC level. The House owner Mr. Gopi Krishna Karki has received second tranche and forwarded the file for third tranche, But the file for third tranche has been rejected. Two story building with mud mortar leads the problem to get the final tranche, the house owner complained about the technical supervisor, he told us "I have constructed this house with collection the advice from the technical person but these day I could not able to get my third tranche by showing this full structure". He asks for recommendation that how he can get the final tranche.



Ward 3, Molung Rural municipality, Okhaldhunga: Stone masonry structure in mud mortar and wooden horizontal bands in lintel and seal level. Kamal Parsad Phuyal the house owner constructed this house immediate after the earthquake i: e early January of 2016. Without supervised and technical guidance, he had constructed this house having two stories. The house owner has only received first tranche and rejected for second tranche. We gather the information from the Ward chairperson Ram Karki he told us, in this ward 14 numbers of houses have problem in getting second and third tranche.



Ward 5, Molung Rural municipality, Okhaldhunga: Tika Bahadur Tamang house owner has received second



Ward 2, Molung Rural municipality, Okhaldhunga:

tranche and transferred the file for third tranche. Stone masonry structure in mud mortar and wooden bands used to construct the house. Technical person recommended Mr. Tamang to correct the height of the house, he has corrected by providing the wooden vertical member to join the upper horizontal and lintel horizontal band.

The owner of composite hybrid structure is Cheena Maya Khatri. The lower part constructed with stone masonry in mud mortar providing concrete horizontal band and upper part constructed with the wooden frame with CGI partition. She has received second tranche. Technical person who has working in this ward do not have inspection form and, they are bit confusing about this type of structure to transfer the file.